

10/ 688550



PATENT

6,931,345 B1

11461.00.5779

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Jonggook Kim et al.

U.S. Patent No.: 6,931,345 B1

Issued: August 16, 2005

For: METHOD FOR
QUANTIFYING SAFE
OPERATING AREA FOR
BIPOLAR JUNCTION
TRANSISTOR

Examiner: John Le

Certificate
SEP 06 2005
of Correction

REQUEST FOR CERTIFICATE OF
CORRECTION OF PATENT FOR PTO
MISTAKE 37 CFR § 1.322(a)

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450
Attn: Certificate of Correction Branch

Certificate of First Class Mailing
I hereby certify that this paper (Request For Cert. Of
Correction) and Certificate of Correction 1 page) are
being deposited with the United States Postal Service as
first-class mail in an envelope addressed to: Comm. For
Patents, P.O. Box 1450, Alexandria, VA 22313-1450,
Cert. of Corr. Branch.
8/29/05
Nanette W. Combs
Date Nanette W. Combs

Sir:

Attached is Form PTO/SB/44 with errors and changes requested.

The exact location where the errors occur in the Certificate of Correction is:

Column 1, line 58

Column 4, lines 25 and 35

Column 5, lines 32, 39, 45 and 61

SEP 07 2005

6,931,345 B1

PATENT

11461.00.5779

Please send the corrected Certificate to:


Mark A. Dalla Valle, Esq.
Vedder, Price, Kaufman & Kammholz, P.C.
222 North LaSalle Street, 24th Floor
Chicago, IL 60601

The Commissioner is hereby authorized to charge any additional fees to
Deposit Account Number 22-0259.

Respectfully submitted,

VEDDER, PRICE, KAUFMAN & KAMMHOLZ, P.C.

Date: Aug. 29, 2005

By: 

Mark A. Dalla Valle
Reg. No. 34,147

Attorney for Assignee
222 N. LaSalle St.
Chicago, IL 60601
Telephone: 312-609-7500
Facsimile: 312-609-5005
Customer No. 23418
Atty. Docket: 11461.00.5779

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 6,931,345 **61**
APPLICATION NO.: 10/688,550
ISSUE DATE : August 16, 2005
INVENTOR(S) : Jonggook Kim, Yun Liu and Joseph A. De Santis

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, line 58, delete "lee" and insert --lee--.

Column 4:

line 25, delete "lout" and insert --lout--.
line 35, delete "lout" and insert --lout--.

Column 5:

line 32, delete "lout" and insert --lout--.
line 39, delete "lout" and insert --lout--.
line 45, delete "lout" and insert --lout--.
line 61, delete "(lout)" and insert --(lout)--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Mark A. Dalla Valle, Vedder, Price, Kaufman & Kammholz, P.C.
222 N. LaSalle St.
Chicago, IL 60601

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

1409834
P05779

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

SEP 07 2005